



Plate 1: General view of site, showing relationship between residential block and the ruined "New Tower", looking N (photo 1/15).



Plate 2: South elevation prior to vegetation removal and consolidation, looking N (photo 1/1).



Plate 3: View into room E prior to consolidation, looking S (photo 1/16).



Plate 4: View into lobby (A) prior to consolidation, looking E (photo 1/11).





Plate 5: Part of west elevation prior to vegetation clearance and consolidation, looking E (photo 1/8).



Plate 6: West side of room D prior to consolidation, looking W (photo 2/4).





Plate 7: South elevation after consolidation, looking N (photo 7/1).



Plate 8: View into room E after consolidation, looking S (photo 7/13).